

2 TAXI TESTS (AN211-2002)

Reference is made to paragraph 2 of the minute of meeting of the Taxi Liaison Group of 14th March 2002 wherein it was agreed that consideration be given to identifying minor defects resulting in a test failure for which a retest fee would not be levied.

Following a meeting with the DTA it is recommended that no retest fee be levied for any of the following, subject to there being no more than three defects found at the time of test.

Defective lamp (including roof sign)

Defective horn

Defective wiper blade

Defective registration plate

Missing mud flap

Missing wheel trim.